SIL 04_2010_MAS-100® NT

1 Mounting instruction for Connector PCB

The original thread-forming screws can not be used twice. The screw thread could be damaged!

For a replacement of the Connector PCB in the MAS-100® NT units, please use only the delivered accessories and replace the old parts.

- Connector PCB	PN 06.8702.01
- Screw M 2.5x5 (A2)	PN 92.0060.00
- Washer M2.5 (A2)	PN 92.0061.00



Stäfa, 02.06.2010

MBV AG
Cedomir Krndija
QM