



AIR. NOTHING ELSE.

DISCONTINUATION OF PRODUCTION OF THE DA-100 NT DIGITAL ANEMOMETER

SERVICE INFORMATION LETTER 2020_01 V2.0

Product affected: DA-100 NT

Change level:

- ☐ mandatory
- ☐ recommended by MBV
- ☒ for information only

1. REASON

This document describes the end of production of the DA-100 NT Digital Anemometer and the implications on future availability, service and support.

2. END OF PRODUCTION OF THE DA-100 NT DIGITAL ANEMOMETER

Order and delivery: The production of the DA-100 NT Digital Anemometer has been discontinued with immediate effect. No DA-100 NT anemometers can be ordered, and none will be delivered by MBV.

A replacement product to the DA-100 NT was announced via [SIL 2020_02 MAS-100 Regulus introduction](https://www.mbv.ch/media/sil_2020_02_mas-100_regulus_introduction.pdf) (https://www.mbv.ch/media/sil_2020_02_mas-100_regulus_introduction.pdf).

Repair Service: Repair will be guaranteed until 2025-06-30 after this date, repair operations will be discontinued.

Calibration Service: Airflow calibration of DA-100 NT as well as its predecessor DA-100 will be carried out by MBV in the future. No end date for such services has been defined or communicated. The calibration depends on the technical condition of the instrument. If this is too poor, calibration cannot be guaranteed.

Further information: Stay informed and register to our newsletter: www.mbv.ch

MBV AG

Stäfa, 2024-11-19 CHA